

Textile Care



The product may be machine washed at a maximum bath temperature of 40°C. Mechanical action, rinsing in water up to 40°C, and spinning correspond to the normal washing machine cycle.



The product may be machine washed at a maximum bath temperature of 60°C. Mechanical action, rinsing in water up to 60°C, and spinning correspond to the normal washing machine cycle.



The product may be boiled. When machine washed, no special care is required. Mechanical action, rinsing without temperature control, and spinning correspond to the normal washing machine cycle.



The temperature of the soleplate of the iron must not exceed 110°C.



The temperature of the soleplate of the iron must not exceed 150°C.



The temperature of the soleplate of the iron must not exceed 200°C.



The product must not be ironed.



The product may be bleached with agents releasing chlorine.



The product must not be bleached with agents releasing chlorine.



The product may be dry cleaned using tetrachloroethene (perchloroethylene), benzine, trifluorotrichloroethane, or fluorotrichloromethane by standard cleaning procedures.



The product must not be dry cleaned.



The product can be tumble-dried at a low drying temperature.



The product must not be tumble-dried.



The damp product must be dried exclusively by hanging.